LS-4005 Series Scanner on 4694 Register

Note: Eject the boot disk and boot up the register. When a message is displayed
indicating the register can't find a boot device, scan the programming codes,
properly insert the boot disk, and tap the SALE key to finish booting.

SET ALL DEFAULTS

Page 5-7

Port 9B

Page 5-8

**CONVERT UPC-E TO UPC-A
(ENABLE)**

Page 5-31

DECODE UPC/EAN WITH SUPPLEMENTALS

Page 5-26

AUTODISCRIMINATE UPC/EAN SUPPLEMENTALS

Page 5-26